S/N: 10/711,957

Reply to Office Action of December 18, 2006

Amendments to the Specification:

Please amend numbered paragraph 26, as shown below:

The bracket 36 includes a receptacle portion 58 that receives the rib 50 formed on the outer surface 44 of the bushing 38. The receptacle portion 58 has a right inner face 60 and a left inner face 62 that engage the sides of the rib 50. The rib 50 centers the bushing 38 relative to the bracket 36 and retains bushing 38 within the bracket 36. The bracket 36 has flanges 64 with holes 66 for receiving bolts 68 [[70]] or other fasteners.